



HITACHI



DK209 Series 2.5-inch ATA-4 Hard Disk Drives

Model			DK239A-48	DK239A-65	DK229A-10
Performance	Specifications				
Total Capacity Formatted		4.87 GB	6.49 GB	10 GB	
		Per Sector		512 Bytes	
Number of Cyline	ders			11,141	
Number of Disks		2 (Thin Film)		3 (Thin Film)	
Number of Heads			3 (Giant Magneto Resistive)	4 (Giant Magneto Resistive)	6 (Giant Magneto Resistive)
Seek Time (Nominal)		Average	12 ms		
		Maximum	24 ms		
		Minimum	3 ms		
Average Latency		7.1 ms			
Rotational Speed		4,200 rpm			
Read Technology			MEEPRML ID - Less Format		
Internal Transfer Rate		10.0 - 16.3 MB/s		10.3 - 16.6 MB/s	
Areal Density		6.15 GBits/in ²		6.29 Gbits/in ²	
Recording Density		315,300 bpi		323,000 bpi	
Track Density		19,500 tpi			
Interface		ATA-4			
Interface Transfer Rate		16.6 MB/s max. (PIO Mode 4, DMA Mode 2) / 33.3 MB/s (Ultra DMA 2)			
Data Buffer		512 kB (R/W Segmented Cache)			
Dimensions	Height Width		9.5 mm 70.0 mm		12.7 mm 70.0 mm
					70.0 mm 100.0 mm
Maiaht	Depth			<u>) mm</u>	130 g
Weight Power Requirements +5V±5% Power Consumption		Seek	99 g		0.43 A (typ.)
		Spin-up	0.42 A (typ.)		0.9 A (ytp.)
		Idle	0.9 A (typ.) 0.15 A (typ.)		0.16 A (typ.)
		Sleep			0.02 A (typ.)
		R/W	0.02 A		0.42 A (typ.)
		Stand-by	0.41 A		0.05 A (typ.)
		Low Power Active	0.05 A		0.34 A (typ.)
		Idle	0.33 A		0.80 W
Energy Consump		1010			0.000080 W/MB
znergy demourn	Temperature	Operating	0.00012 W/MB 0.000080 W/MB 5 to 55°C (41 to 131°F)		
Environmental Conditions	romporataro	Non-Operating	- 40 to 70°C (- 40 to 158°F)		
	Relative Humidity			5 to 90%	
	relative Harriarty	Non-Operating	5 to 90%		
		Max. Wet Bulb	29°C (84.2°F) (non-condensing)		
	Shock	Operating	150 G or less (2 m	, , ,	125 G or less (2 ms half sine
		Non-Operating		000 G or less (2 ms half sine wave)	· · · · · · · · · · · · · · · · · · ·
	Vibration	Operating	0.5 G or less (22 - 400 Hz)		
		Non-Operating	5 G or less (22 - 400 Hz)		
Acoustic Noise Idle		27 dBA (typ.)			
				\J: /	
Reliability Preventive Maintenance			Not Required		
Error Rate (Unrecoverable Errors)			less than 1 per 10 ¹³ bits read		
(

HITACHI

Eastern U.S. Hitachi America, Ltd. 1601 Trapelo Road Waltham, MA 02154 Tel. (781) 890-0804 Fax. (781) 890-6677 Northwestern U.S. Hitachi America, Ltd. 2000 Sierra Point Parkway, MS: 600 Brisbane, CA 94005-1835 Tel. (650) 244-7610

Fax. (650) 244-7450

Southwestern U.S.Hitachi America, Ltd.
1215 W. Imperial Hwy, Ste. 202
Brea, CA 92821
Tel. (714) 680-8367
Fax. (714) 871-8443

Canada Hitachi (Canadian) Ltd. 6740 Campobello Road Mississauga, Ontario L5N 2L8 Tel. (905) 826-4100 Fax. (905) 826-8818